

## **Incident Action Details**



Generated on Monday, 17 August 2009

Incident Details Summary

**Ref No:** SI-112 **Status:** Pending **Type:** Site Improvement

Name: Symeoy, Anthony Date: 27 May 09 State: VIC

**IIR Location:** Mt Franklin

**Summary:** Corrective action IIR for Audit AUD-1035

**Description:** Audit: AUD-1035

Type: Rig Inspection (TLD Rig 6) Category: Rig Inspection

Program: Inspection/Testing Program

**Employees:** 

Category: Rig Improvement Severity: Minor

Assigned To: Arthur, Justin Date: 28 May 09 Action By:

## **Action Title: Corrective Action**

Cause and Corrective / Preventative Details

Action Type: Corrective Action Action Status: Allocated

Action: Corrective action IIR for Audit AUD-1035

Actioned Date: Costing:

Sub-Action: Replace Control panel sign for Rod Action By Date: 30 Jun 09

Clamp & Boom

Assigned To: Brunt, Rodney Actioned Date:

Comments: Sign Scratched & fading. See Blue on actions

Sub-Action: Replace Fire extinguisher for Rig Ute. Action By Date: 05 Jun 09
Assigned To: Brunt, Rodney Actioned Date: 28 May 09

Comments: Also plan for Fire extinguishers on rig to be Tested/Tagged as there 3 due next month

Sub-Action: Order new Chemical Storage Sign Action By Date: 28 May 09

Assigned To: Brunt, Rodney Actioned Date: 28 May 09

Comments: Spare sign in Rocket's Office

**Sub-Action:** Replace spray bottles which are **Action By Date:** 04 Jun 09

currently being used for spraying Armorall/Spray & wipe, as they don't have proper chemical labels on them.

Assigned To: Brunt, Rodney Actioned Date: 28 May 09

**Comments:** Rocket to consider ordering smaller bottles with proper labels and not the refill ones.

Sub-Action: Order Battery Isolation sticker for Rig Action By Date: 12 Jun 09
Assigned To: Brunt, Rodney Actioned Date: 29 May 09

Comments: Stickers ordered and should be ready on 30/5/09

Sub-Action: Grinder to be tested & tagged Action By Date: 01 Jun 09
Assigned To: Brunt, Rodney Actioned Date: 01 Jun 09

Comments: Grinder is not be used until testing & tagging completed. Grinder cord fray and needs replacing

Generated on Monday, 17 August 2009

**Sub-Action:** Guarding required for Rig Motor's fan

belts, wireline & Bean Pump

Action By Date: 30 Jun 09

Action By Date: 05 Jun 09

Assigned To: Brunt, Rodney Actioned Date:

Comments: Blue to organise measurements for guarding. See Blue on Actions

**Sub-Action:** Hiab Lifting chain to be replaced or

retested for weight limits

Assigned To: Brunt, Rodney Actioned Date: 28 May 09

Comments: Lifting chain information emailed to Russell on 28/5/09 by Tony S

Sub-Action: Laminate TLD emergency Contact

Procedure

Action By Date: 29 May 09

**Assigned To:** Symeoy, Anthony **Actioned Date:** 28 May 09

**Sub-Action:** Update Book with new Toolbox

Meeting Format

Action By Date: 29 May 09

Assigned To: Symeoy, Anthony Actioned Date: 28 May 09

Sub-Action: Replace or repair Rig phone Action By Date: 29 May 09
Assigned To: Gavin, Stephen (Blue) Actioned Date: 29 Jun 09

Assigned To: Arthur, Justin Responsible: O'Connor, Tim

Delegate: Complete by Date: 30 Jun 09

Reviewer: Review Date:

Completion:

Follow-Up		
Person:	Follow-up by Date:	
Status:	Close-off Date:	
Comments:		
Report:		
Audit No:	Risk Assessment:	