



Client:	DPI		Prospect:		Southern Flank 2D				Line No:	DPISF-060-P1035		
Line Details									Date:	06 Mar 10		
Time	SP	File	Reel	Error	Comments				RMS Noise	W/Depth	Feather	
UTC									μB	m	°	
9:58					Gun Arrays Soft Start.							
10:33					Soft Start Complete.							
		5017	37		BOT, Noise Test				2.6			
		5016			Noise Test				2.5			
10:40	5015	5015			FSP							
10:42	4995	4995			FGSP, FCSP, SOL					864.8	-1.5°	
	4324	4324			Gun #1-4 (60 cu.in) failed to detect fire, Good SP, verified by QC processing							
	3900	3900			Bend noise observed at front of streamer and moving down to ch 330, d/t strong current							
	3670	3670			Bend noise no longer visible							
	3448	3448			FA >10						10.1°	
	3104	3104			FA Max						12.7°	
	2665	2655			FA <10						9.9°	
17:26	1001	1001			LFFSP					34.48	-1.3°	
17:40	865	865			LGSP					34.14	-2.5°	
17:40	863	863			LSP. EOL							
		862			Noise Test				3.0			
		861	37		Noise Test, EOT				3.1			
				☑	Cross checked with Navigation							
					LINE COMPLETE							