

### 21 Sep 2008

Г

From: B. Openshaw / R. Rossouw To: R. Oliver135000

### DRILLING MORNING REPORT # 4 BAZZARD-1

Well Data										
Country	Australia	MDBRT	154.0m	Cur. Hole Size	36.000in	AFE Cost	AUD\$16,336,000			
Field	Bazzard	TVDBRT	0.0m	Last Casing OD		AFE No.	Case 1: Rev B			
Drill Co.	Seadrill	Progress	47.6m	Shoe TVDBRT		Daily Cost	AUD\$834,140			
Rig	West Triton	Days from spud	1.02	Shoe MDBRT	151.8m	Cum Cost	AUD\$2,680,332			
Wtr Dpth (MSL)	68.000m	Days on well	3.21	FIT/LOT:	/					
RT-MSL	38.000m	Planned TD MD	3500.000m	Current Op @ 0600	Picking up	Picking up 5.5" DP from catwalk.				
RT-ML	106.000m	Planned TD TVDRT	3500.000m	Planned Op	Continue picking up approx 800m DP, make u 18.75" wellhead assy. Pick up 16" BHA.					

### Summary of Period 0000 to 2400 Hrs

Waited on slack tide and continued spudding well. Drilled to 154m, swept and filled hole with gel mud and performed wiper trip. Displaced a further 200bbl gel mud to hole and POOH laying down bit, H /opener and Anderdrift tool. Rigged up and ran 30" conductor to 151.8m. Made up Icon clamp above CTU and cut conductor above clamp. Laid out excess conductor and RIH with cement stinger.

HSE Summary				
Events	Num. Events	Days Since	Descr.	Remarks
Abandon Drill		3 Days	Held at 10.40 hours.	Abandon ship drill prior to rig move. Good responce by all crews.
BOP Test	1	0 Days	Pressure tested BOPs.	21 Days - 12 Oct 08
First Aid Case		25 Days	Third Party received small laceration to top of right thumb.	
Incident		0 Days	Pinion gear on TDS fell to rig floor.	A pinion gear of the rotating head on the TDS, weighing 14kg, sheared its shaft and fell 5m to the rig floor. Nobody on rig floor at the time.
PTW issued	15	0 Days		Permit to work issued for the day.
Safety Meeting		4 Days	Pre-tow meeting	Pre-tow meeting to discuss towing operations with related parties.
Safety Meeting		1 Day	Weekly safety meeting	Weekly safety meeting
STOP Card	19	0 Days		Stop cards submitted for the day.

### Operations For Period 0000 Hrs to 2400 Hrs on 21 Sep 2008

Phse	Cls (RC)	Ор	From	То	Hrs	Depth	Activity Description
P2	Р	G25	0000	0100	1.00	112.0m	POOH to 109m and waited on slack tide to improve drillstring angle.
P2	Ρ	D2	0100	0500	4.00	154.0m	Drilled ahead from 109m using very low weights (1.5Klbs) to 121m pumping 75bbl hi-vis sweep at 113m. Took survey at 121m - 1.5 deg. Continued drilling with very low weight from 121m to 154m pumping 75bbl hi-vis sweeps at every single. Took survey at 152m - 1 deg.
P2	Р	F3	0500	0530	0.50	154.0m	Pumped 150bbl hi-vis sweep and then displaced hole with 200bbl prehydrated bentonite.
P2	Р	G8	0530	0600	0.50	154.0m	Performed wiper trip to 109m and back to bottom - OK.
P2	Р	F3	0600	0630	0.50	154.0m	Pumped 200bbl prehydrated gel to displace hole.
P2	Р	G9	0630	0830	2.00	154.0m	POOH and laid down bit, hole opener and Anderdrift tool.
P3	Р	G1	0830	1000	1.50	154.0m	Rigged up to run 30" conductor.
P3	Р	G9	1000	1700	7.00	154.0m	Held PJSM and ran 30" conductor casing to 151.8m
P3	Р	G9	1700	2030	3.50	154.0m	Made up Icon clamp on CTU and torqued up same.
							Incident: At approx 20h00, pinion gear of rotating head broke off TDS and fell 5m to rig floor - see HSE section of this report.
P2	Р	G9	2030	2130	1.00	154.0m	Cut 30" conductor 2m above Icon clamp and laid down first joint of conductor.
P2	TP (RE)	G9	2130	2200	0.50	154.0m	Reposition and tighten link tilt clamps on bail arms due to slippage.
P3	Р	G9	2200	2300	1.00	154.0m	Laid down last jnt of conductor casing, rigged down W/ford and rigged up for 5.5" DP.
P3	Р	G1	2300	2400	1.00	154.0m	RIH with stinger and cementing head assy.

Operations For Period 0000 Hrs to 0600 Hrs on 22 Sep 2008



Phse	Cls (RC)	Ор	From	То	Hrs	Depth	Activity Description
P3	Ρ	G1	0000	0130	1.50	154.0m	Continued RIH with stinger, broke circulation and stung into 20" shoe at 151m. Filled 30" conductor with seawater to check integrity of stinger seals.
P3	Ρ	F3	0130	0330	2.00	154.0m	Cemented 30" conductor. No seabed observation due to suitcase ROV unable to cope with sea conditions. Pumped 10bbl seawater and pressure tested lines to 1000psi. Pumped 110bbl seawater ahead. Mixed and pumped 240bbl class G cement at 15.9ppg. Displaced cement with 10bbl seawater - final pumping pressure at end of displacement: 140psi. Checked for backflow - negative - unstung and flushed stinger with further 10bbl seawater. Rigged down lines on rig floor.
P3	TP (RE)	G1	0330	0400	0.50	154.0m	Unable to unscrew TDS from top of cementing head stand due to failure of rotating head gear. Broke out pipe from TDS using rig tongs.
P3	Р	G1	0400	0530	1.50	154.0m	POOH cement stinger and racked back same.
P4	Р	G2	0530	0600	0.50	154.0m	Held PJSM and commenced picking up 5.5" DP from catwalk.

## Operations For Period Hrs to Hrs on

Phase Data to 2400hrs, 21 Sep 2008						
Phase	Phase Hrs	Start On	Finish On	Cum Hrs	Cum Days	Max Depth
Mob/Demob(P1)	38.5	18 Sep 2008	20 Sep 2008	38.50	1.604	0.0m
Conductor Hole(P2)	24.5	20 Sep 2008	21 Sep 2008	63.00	2.625	154.0m
Conductor Casing(P3)	14	21 Sep 2008	21 Sep 2008	77.00	3.208	154.0m

### **General Comments**

## 00:00 TO 24:00 Hrs ON 21 Sep 2008

00.00 TO 24.00 HIS ON 21 Sep 200	0
	West Triton Rig Equipment Concerns
	1) Top drive rotating head has operating problems, to be able to rotate the IBOP must be operated first. This is impacting operational efficiency. Pinion gear has sheared its shaft and broken off.
	2) CTU control panel has leaking valves, pressure regulator valve inoperable. Parts on order.
	3) Link tilt clamps slipping on bails - need to rectify this issue.
	4) Number 4 main generator down. Exciter and generator sent ashore.
Operational Comments	5) Emergency generator fuel tank requires modification to drain line (no communication with tank through drain line).
	6) Cyber chair pressure guages for the standpipe & choke manifolds require calibration.
	7) Remote controller for Iron Roughneck not operational _ new one on order.
	8) Battery charger on Port crane not operational.
	9) Need to investigate possible misalignment of dolly beams and dolly rollers on Top Drive System. Requires shimming. A derrick alignment survey has been completed. Shims have been ordered to rectify alignment problem and these will be fitted as soon as they arrive.
	10) Large pressure discrepancy on operating pressure for annular between rig floor and unit.

# 

WBM Data				Cost Toda	y AUD\$ 772	1			
Mud Type:	Pre-hydrated	API FL:	18.0cc/30min	CI:	2300mg/l	Solids(%vol):	2%	Viscosity	200sec/qt
	Bentonite	Filter-Cake:	2/32nd"	K+C*1000:	-	H2O:	98%	PV YP	20cp 70lb/100ft <sup>2</sup>
Sample-From:	Pit #3	HTHP-FL:		Hard/Ca:	280mg/l	Oil(%):		Gels 10s	55
Time:	23:00	HTHP-cake:		MBT:	36	Sand:		Gels 10m	60
Weight:	8.70sq	HIHF-Cake.		IVID I.	50	Sanu.		Fann 003	52
0	0			PM:	0.5	pH:	9	Fann 006	55
Temp:	22C°			PF:	0.12	PHPA:		Fann 100	70
					0.12	1 HI A.		Fann 200	85
Comment						ogrammed. Pump 15		Fann 300	90
sweep at TD and the displace hole with 200bbl PHB mud. Returns to seabed. After wiper trip, circulate seawater and displace hole with 200bbl PHB. Commence mixing PHB for next section Received 40 MT Bentonite from Valkyrie.								Fann 600	110



Bit # 1					W	ear	I		01		D	L		В	G	0	2	R
							1		1	v	VT	А		NB	Ι	N	C	TD
					Bitw	/ear Co	ommen	nts:										
Size ("):	26	.00in	IADC#	1-1-1		Nozz	zles		Dril	led ov	er las	t 24 hr	s	Ca	Iculate	d over	Bit Ru	in
Mfr:	R	REED	WOB(avg)	3.00klb	No.		Size		Progre	ess		47.	6m (	Cum. Pr	ogress			47.6m
Туре:		Rock	RPM(avg)	70	1		16/32	2nd"	On Bo	ottom H	Irs	2	.6h (	Cum. Oi	n Btm H	Irs		2.6h
Serial No.:	Q3	4406	F.Rate	1100gpm	3		22/32	2nd"	IADC	Drill H	rs	4	.0h (	Cum IAI	DC Dril	Hrs		4.0h
Bit Model	`	Y11C	SPP	1400psi					Total	Revs			(	Cum To	tal Rev	s		0
Depth In	10	6.4m	HSI						ROP(	avq)	1	8.31 m	/hr l	ROP(av	a)		18.3	81 m/hr
Depth Out	15	4.0m	TFA	1.310					```	0,					0/			
Bit Comment																		
BHA # 1																		
Weight(Wet)	38.0	00klb	Length			123.0	)m To	orque	(max)			2000ft-	lbs [	D.C. (1)	Ann V	elocity		46fpm
Wt Below Jar(Wet)			String			98.00k			(Off.Bt	tm)				D.C. (2)				44fpm
			Pick-Up						(On.Bt			1500ft-		H.W.D.F				42fpm
			Slack-Off					0.940	(0	)				D.P. Ani				42fpm
BHA Run Description	1		26"bit, 36"	H/O Float	sub	Anderd	drift 2 x	(95"	DC's	x-over	4 x 8	1/4" D(						12 ipin
BHA Run Comment			20 51, 00	1,0,1104	. 000,		, <u> </u>	( 0.0	200,		, 120		, x			•••		
	Equipmen	t		Len	ath	OE	D C	IC	)	S	Serial #	4			Con	nment		
Bit	- 40.p				58m	26.0				34406								
Hole Opener					65m		00in			01100								
Float Sub				1.:	23m	9.5	50in											
Pulser				3.	35m		44in			ADB9	113							
Drill Collar					86m		50in		06in									
X/O					22m		50in			7124								
Drill Collar X/O					80m 93m		25in 25in		88in 81in	7131								
HWDP					36m		50in		25in	1151								
Bulk Stocks									I									
		Name					ι	Jnit			In		Use	d	Adju	ust	Bala	ance
Drill Water						MT						0		109		0		212.0
Rig Fuel						m3					1	10		13		0		253.0
POTABLE WATER						MT	-				1	15		23		0		258.0
Cement class \'G\'						MT						0		0		0		52.0
Bentonite						MT						40		17		0		46.0
Barite Brine						MT						0		0		0		65.0
BLENDED CEMENT						m3 MT						0 0		0		0 0		10.0 43.0
Pumps										1								
Pump Data - Last 24	Hrs						Slow	v Pun	np Dat	a								
No. Type	Liner (in)	MW (sg)			PP osi)	Flow (gpm)	Dep (m)		SPM1 SPM)	SPP (psi)			SPM2 SPM)	SPP2 (psi)		SPM3 (SPM)		
1 National 14 P-220	6.50	1.02	97	102 16	650	600			20			117	30		176	40		234
2 National 14 P-220	6.50	1.02	97	102 16	650	600			20			117	30		176	40		234
3 National 14 P-220	6.50	1.02	97						20			117	30		176	40		234
Casing	I		•	I	<u> </u>						1	1						
OD LOT	/ FIT	Csg	Shoe (MD	/TVD)							Cen	nenting						
30 " /		-	2.00m / 152															



# Personnel On Board

Company	Pax
ADA	4
Seadrill	14
Seadrill Services.	36
Catering	9
Halliburton - Sperry	2
Baker Hughes Inteq	2
Halliburton - Sperry	2
Tamboritha	4
Dril-Quip	3
OPC	2
Schlumberger MWD/LWD	3
Weatherford	2
ROV-UIS	1
Total	84

Mud Volu Shaker D		l Losses a	nd Shale		Engin	eer : Gerald	Lange/Tim V	Valdhuter				
Available	1384.3	bbl Losses	92	7.3bbl	Ec	quipment	Description		Mesh Size	Comm	ents	
Active	336.0	bbl Downho	le		Shaker 1		VSM-300		89			
	00010			0.0661	Shaker 1		VSM-300		89			
Mixing		Surf+ Ed		0.0bbl	Shaker 2		VSM-300		89			
Hole	198.3	bbl Dumped	Dumped 927.3bbl		Shake	er 2	VSM-300		89			
Slug Reserve	850.0	bbl De-Gas	De-Gasser De-Sander		Shake	er 3	VSM-300		89			
	000.0				Shake	er 3	VSM-300		89			
Kill		De-Silte Centrifu	r ge		Shake	er 4	VSM-300		89			
			-		Shake	er 4	VSM-300		89			
Marine												
Weather on	21 Sep 2008											
Visibility	Wind Speed	Wind Dir.	Pressure	Air Ter	mp.	Wave Height	Wave Dir.	Wave Period				
10.0nm	22kn	207.0deg	1002.0mbar	15C	0	1.0m	240.0deg	4s	_			
Rig Dir.	Ris. Tension	VDL	Swell Height	Swell I	Dir.	Swell Period	Weather	Comments	_			
133.5deg	150.00klb	2211.00klb	1.5m	240.00	deg	4s	Wave and swell heights					
		Com	ments				are es	timates.				
Vessel I	Name Ar	rived (Date/		Departed ate/Tim		Sta	tus	Bulks				
Pacific Battle	r					At rig.		Iten	n U	Init	Used	Quantity
								Rig Fuel		m3		347.7
								Potable Water Drill Water		Mt Mt		450 90
								CEMENT G		Mt		42
								Barite		Mt		42
								Bentonite SOBM		Mt m3		42
								Brine		m3		110
Desifie Mall	-1-					En muta O	-l					
Pacific Valky	rie					En route Ge	0	Item		nit	Used	Quantity
								Rig Fuel Potable Water		m3 Mt		394 205
								Drill Water		m3		0
								CEMENT G		Mt		0
								Barite		Mt Mt		70
								Bentonite SOBM		Mt m3		0
								Base Oil		m3		0
								Brine		m3		0