



Figure 3 MRIL T2 distribution in residual gas column shows decreased signal amplitude above Marlin original gas-water contact, 1581 metres. Strong uni-modal signal amplitude throughout high porosity sand may be caused by bulk fluid T2 relaxation.

DEPT. NAT. RES & ENV



PE906513