



Generated on Monday, 17 August 2009

Incident			
Ref No: F	PE-148	Status: Raised	Type: Property/Equipment Damage/Loss
Identification De	tails		Incident Date/Time/Location
Name: (D'Connor, Tim		Date: 24 Jul 2009 Time: 11:00 AM
ID No: 3	39	External:	Address: Moolort
Location: ા	Jnspecified		Location: Ballarat
Source:		Grid Ref:	State/Ctry: VIC Region: Australia
Reported: 2	24 Jul 2009	Job No:	Site Type: Rig 13-TLD
Incident / Improvement Details			
	Rods/Cassing	Level: 2	Severity Minor
	-	n the sides and snapped of	-
Description: While drilling through sands on hole No. GV-2 at 65mts down, basement was tagged and Bit blocked off. Pulled out to run PQ barrel to find that PCD bit had worn on the sides snapping it off Injury: Near Miss: Improvement: Environmental: Manual Handling: Asset Damage: X Contractor: Employees:			
Contractors:			
Division:	Fiteline Drilling		Function:
Task:	Contract No:		
Risk Assess:		Audit No:	Costing:
Plan. Project:		Proj. Phase:	Project Task:
Assigned To:		Delegate:	Assigned Date:
		Action By Date:	Close-off Date:
Investigation De	tails		
Cause Cat:		Equip No	Plant No:
Cause Desc:			
Likelihood:		Consec	Re-occur Rat:
Exposure:		Persons	Risk No:
Report Doc:		Survey Answers	;:
Survey Rating:		Answering Employee):