

Figure 3a

Porosity is generally better where feldspar and quartz grains are in contact. Pores are lined with blades of green chlorite (arrow). Swc 11, depth 1412m. Plane light. Field of view 1mm.




Figure 3b

As above under crossed nicols. Feldspars are variably altered and some are fractured. Fractures are usually filled with chlorite.

