


2

3

GLENAIRE-1 Time Depth Chart



- Drill 17 1/2" surface hole to 307m
- Run and set 13 3/8" surface casing
- Drill 12 1/4" hole to 1255m
- 5. Run & set 9 5/8" casing.

