

EAPL WellWork Daily Operations Report

Daily Operations: 24 HRS to 3/03/2007 06:00

Well Name Bream A21A			
Rig Name Rig 22		Company Imperial Snubbing Services	
Job Subcategory		Plan Plug & Abandon	
Report Start Date/Time 2/03/2007 06:00		Report End Date/Time 3/03/2007 06:00	Report Number 4
AFE or Job Number 40000469	Currency AUD	Total Original AFE Amount 920,500	Total AFE Supplement Amount
Days Ahead/Behind 4.0		Daily Cost Total 133,065	Cumulative Cost 312,217
Management Summary Schlumberger cut tubing above packer at 2726.1m. Rig down Schlumberger and circulate well clean. POOH with redundant 3-1/2" tubing to sssv. RIH with drill pipe to HUD at 2728m. Pump 12 bbls cement and reverse circulate well to ISW, tag TOC at 2658m. POOH with drill pipe and lay out.			
Activity at Report Time Lay out drill pipe			
Next Activity Lay out tubing			

Daily Operations: 24 HRS to 4/03/2007 06:00

Well Name Bream A21A			
Rig Name Rig 22		Company Imperial Snubbing Services	
Job Subcategory		Plan Plug & Abandon	
Report Start Date/Time 3/03/2007 06:00		Report End Date/Time 4/03/2007 06:00	Report Number 5
AFE or Job Number 40000469	Currency AUD	Total Original AFE Amount 920,500	Total AFE Supplement Amount
Days Ahead/Behind 3.5		Daily Cost Total 78,378	Cumulative Cost 390,595
Management Summary POOH and lay out 4" drill pipe and redundant 3-1/2" tubing. Nipple down BOPs and riser. Nipple up abandonment flange, hand well back to Production.			
Activity at Report Time Rigging down riser and preparing for aband flange			
Next Activity Lay out drill pipe from derrick			

Daily Operations: 24 HRS to 5/03/2007 06:00

Well Name Snapper A19			
Rig Name Rig 22		Company Imperial Snubbing Services	
Job Subcategory		Plan Plug and Abandon the A-19	
Report Start Date/Time 4/03/2007 06:00		Report End Date/Time 5/03/2007 06:00	Report Number 1
AFE or Job Number 40000470 - Rig Move.	Currency	Total Original AFE Amount 1,516,470	Total AFE Supplement Amount 1,804,000
Days Ahead/Behind		Daily Cost Total 72,998	Cumulative Cost 72,998
Management Summary Break down 4" drill pipe in mouse hole and prepare for back load. Back load pipe and third party equipment.			
Activity at Report Time Clear rig floor of equipment.			
Next Activity Prepare the scope down mast			

EAPL WellWork Daily Operations Report

Daily Operations: 24 HRS to 3/03/2007 06:00

Well Name Bream B10			
Rig Name Wireline		Company Halliburton / Schlumberger	
Job Subcategory		Plan Replace Xmas tree	
Report Start Date/Time 2/03/2007 06:00		Report End Date/Time 3/03/2007 06:00	Report Number 12
AFE or Job Number 46000482	Currency AUD	Total Original AFE Amount 200,000	Total AFE Supplement Amount
Days Ahead/Behind		Daily Cost Total 18,367	Cumulative Cost 170,337
Management Summary Crews onboard, green card NOPSA . Set plug in XN nipple and bleed tbg pressure down from 11000 kpa to 600 kpa. Exercise Baker TRSSSV			
Activity at Report Time SDFN			
Next Activity Lock out valve, change out gas lift valves, circulate			

Daily Operations: 24 HRS to 4/03/2007 06:00

Well Name Bream B10			
Rig Name Wireline		Company Halliburton / Schlumberger	
Job Subcategory		Plan Replace Xmas tree	
Report Start Date/Time 3/03/2007 06:00		Report End Date/Time 4/03/2007 06:00	Report Number 13
AFE or Job Number 46000482	Currency AUD	Total Original AFE Amount 200,000	Total AFE Supplement Amount
Days Ahead/Behind		Daily Cost Total 18,367	Cumulative Cost 188,704
Management Summary Make several attempts to lock out Baler TRSSV unable to get lock out tool to function.			
Activity at Report Time SDFN			
Next Activity Change out gas lift valves and circulate out to ISW			

Daily Operations: 24 HRS to 5/03/2007 06:00

Well Name Bream B10			
Rig Name Wireline		Company Halliburton / Schlumberger	
Job Subcategory		Plan Replace Xmas tree	
Report Start Date/Time 4/03/2007 06:00		Report End Date/Time 5/03/2007 06:00	Report Number 14
AFE or Job Number 46000482	Currency AUD	Total Original AFE Amount 200,000	Total AFE Supplement Amount
Days Ahead/Behind		Daily Cost Total 18,367	Cumulative Cost 207,071
Management Summary Open TRSSSV and pull circulating valve from GLM at 1061 mts mdr. Circulate 110 bbls ISW. Soft bolt tree and wing valve			
Activity at Report Time SDFN			
Next Activity Complete gas lift valve change out . Test PA and Tbg Set BPV			