

To

'Skunjan@awexp.com.au>,

Buick, Glen" <Glen.Buick@santos.com>,

<drilling.reports@ga.gov.au>, "Clifford, Jenni"

cc

bcc

Subject FW: Henry 2DW1 DGR for 18-09-08

2047m MDRT 1716.0m TVDRT -1695.2m SS MSL

Progress: 339m

0600hrs operations: Circulating hole clean at 311mm (12¼") hole section total depth.

24hr operations: Run in hole. Drill 311mm (12%") directional hole from 1708m to 1998m. Circulate sample out. Drill ahead from 1998m to 2039m. Circulate sample out. Drill ahead 2039m to 2047m. Circulate sample out and confirm penetration of Waarre "A". Circulate hole clean.

Anticipated operations: Pull out of hole. Run and cement 244mm (9 5/8") casing. Pressure test Blow Out Preventers.

I	Surveys	Type	MD (m)	Inclination	Azimuth (T)	TVD (m)	Offset (m)	Direction (T)
•	·	MWD	2005.1	82	115	1710.3	662	117
		MWD	2026.8	82	116	1713.2	683	117

FORMATION	ACTU	AL TOP	High / Low	High / Low	PROGNOSED TOP	
	(mMDRT)	(mSS MSL)	Prognosis (m)	Henry 2	(MDmRT)	(mSS MSL)
K85 UNCONFORMITY	2041.0	-1694.3	0.6 Low	0.6 Low	2014.3	-1693.7
WAARRE A	2041.0	-1694.3	0.6 Low	0.6 Low	2014.3	-1693.7

Jim Day Operations Geology

Santos Ltd Santos Centre 60 Flinders Street Adelaide SA 5000

ph: 08 8116 7752 mob: 0407200747

email: jim.day@santos.com

Santos


Santos Ltd A.B.N. 80 007 550 923

Disclaimer: The information contained in this email is intended only for the use of the person(s) to whom it is addressed and may be confidential or contain privileged information.

If you are not the intended recipient you are hereby notified that any perusal, use, distribution, copying or disclosure is strictly

If you have received this email in error please immediately advise us by return email and delete the email without making a сору.

Please consider the environment before printing this email



Henry 2DW1_Drillog_1600-2047.pdf Henry 2DW1_Mudlog ascii_1628-2047xls Henry-2 DW1 Surveys @ 2047m TDxls