



2-98 Anemone 1A




Figure 16. Anemone #1A, junk sub sample, 4676b m. Thin section micrograph in plane polarized light demonstrating areas of secondary dissolution porosity (d) and fracture porosity (f). Microporosity may well be present. The stylolitic nature of organic matter (and opaques?) is evident. At the left of the photo is a concentration of spar crystals (S).