



Lakes Entrance - 1.

SCHLUMBERGER Electrical log.
Run 2. Woodside Lakes Entrance
No.1 Well.

Resistivity (short normal)

Spontaneous potential



DEPT. NAT. RES & ENV
PE902917

REVISIONS	Date	Remarks	Checked	FIG. 2 - VERTICAL BIO-FACIES SEQUENCE COMPARED WITH E-LOG CHARACTERS WOODSIDE LAKES ENTRANCE No. 1 WELL	Surveyed	DEPARTMENT OF MINES VICTORIA Z	Issue No.
					Drawn <i>C. J. ...</i>		1
					Traced S.W. & C.G.		
					Checked		
REFERENCE				SCALE	Passed	Approved	