

Schlumberger



# GORDON-1

## Fracture Attribute Log

(Scale 1:20)

COMPANY: SANTOS

WELL: Gordon-1

FIELD: Exploration

Victoria

COUNTRY: Australia

Fracture porosity and density log.

Date Processed: 01-May-1997 Date Logged: 29-Apr-1997

Job Number: Processed at: SANTOS DCC

Well Location: Otway Basin PEP 119

Latitude: 37 35' 14.5S Longitude: 141 17' 38.4E

Elevations: KB: 129.59m DF: 129.59m GL: 124.89m

FOLD HERE The well name, location and borehole reference data were furnished by the customer.

All interpretations are opinions based on inferences from electrical or other measurements and we cannot, and do not guarantee the accuracy or correctness of any interpretation, and we shall not, except in the case of gross or willful negligence on our part, be liable or responsible for any loss, costs, damages or expenses incurred or sustained by anyone resulting from any interpretations made by any of our officers, agents or employees. These interpretations are also subject to Clause 4 of our General Terms and Conditions as set out in our current Price Schedule.

