



Figure 5. 1746.3m x75.6 PPL

Quartz sandstone with good intergranular porosity (stained blue). Secondary porosity is also evident within the heavily leached feldspar at F4. Thin detrital clays are also visible coating the primary pore space at H3.

DEPT. NAT. RES & ENV



PE906701