



Figure 10. 1749.6m x75.6 PPL

Massive quartz sandstone. Good primary porosity is evident (stained blue). Thin authigenic silica overgrowths can be seen at F2. The overgrowth can be seen to be coated with detrital clay.

DEPT. NAT. RES & ENV



PE906706