

[GSR82A] [GSR82A--] GSR-82A 1982 G164 6-2-82 TO 27-2-82
ONSHORE GB PEP 102
SION RESOURCES
CONTRACTOR: HORIZON EXPLORATION INTER. VIBROSEIS
100KM QUALITY=VERY POOR
LINES: 82B01, 2, 3, 4, 5, 6, 7

REPORT ON VIBROSEIS SEISMIC REFLECTION SURVEY 290982 G164
PP LINES 1 TO 7 290982

70 1/2" MAGNETIC TAPES FOR LINES: 2, 3, 4, 6, 7 & 1 TAPE LINE S
POST PLOT LISTING FOR LINES 2, 3, 4, 6, 7 (1 BOOK); LINE INTERSECTION DIAGRAM (1 SHEET 1 MAP);
SURVEYOR'S REPORTS LINES: 2, 3, 4, 6, 7 LINE: 5-OBSERVERS FIELD REPORT;
LINES 2, 3, 4, 6, 7: OBSERVERS FIELD REPORT (2) OBSERVERS REPORTS, TVD PLOTS
WIGGLE TRACE BUNDLES FOR LINES 2, 3 (3) 4, 5, 6(2) 7 (9 BUNDLES)
PROVISIONAL PLOTS FOR LINES 6 AND 7; SUB-SURFACE COVERAGE & STATIC CORRECTION
SHEETS FOR LINES 7(2), 6(3), 2(2), 4(4), 3(4)
BALOOK DOME SEISMIC REPORT WITH MAP 290883
9 LOCATION MAPS

G164
G164

{70 1/2" DIGITAL MAGNETIC TAPES: NOS 1-20, 62-92, 106-123, 2226 & 2AI
{BOXES OF POST PLOT LISTINGS, SURVEYORS REPORTS, SUB-SURFACE COVERAGE & STATIC
{CORRECTIONS, OBSERVERS FIELD REPORTS, OBSERVER'S REPORTS, TVD PLOTS, SWEEP
{TESTS, WIGGLE TRACE BUNDLES FOR CERTAIN LINES. PRO LAVERTON 200384