



2-98 Anemone 1A




Figure 3 - Anemone #1A, cuttings, 4530 - 35m. (plane polarized light). The unwashed sample shows a dark globular rim of drilling mud adhering to the chips. Secondary dissolution porosity is evident in an altered perthite grain (1) and a heavily corroded microcline (2).