



Figure 16. 1808.0m x192 XPL

Massive sparry ferroan calcite is evident at H3. This can be seen to display highly corrosive contacts with the detrital quartz grains. Shattered grains and drill mud are visible at D2.

DEPT. NAT. RES & ENV



PE906712