

25 Sep 2005

From: R.King/J. Wrenn To: J. Ah-Cann

DRILLING MORNING REPORT # 51 BASKER - 2

| Well Data | | | | | | | |
|--------------|---------------|--------------------------------------|------------------|----------------------|---------------------|--------------------|------------------------|
| Country | AUSTRALIA | MDBRT | 3,414.0m | Cur. Hole Size | 8.500in | AFE Cost | \$24,733,636 |
| Field | VIC-RL6 | TVDBRT | 3,344.6m | Last Casing OD | 9.625in | AFE No. 3 | 4262-PM-05-AF-01-00 |
| Drill Co. | DOGC | Progress | 0.0m | Shoe TVDBRT | 2,929.0m | Daily Cost | \$C |
| Rig | OCEAN PATRIOT | Days from spud | 42.50 | Shoe MDBRT | 2,945.0m | Cum Cost | \$21,849,668 |
| Wtr Dpth(MS | L) 155.5m | Days on well | 50.79 | FIT/LOT: | 13.10ppg / 0.00ppg | Days Since Las | t LTI 859 |
| RT-ASL(MSL | .) 21.5m | Planned TD MD | 3,414.0m | | | | |
| RT-ML | 177.0m | Planned TD TVDRT | 3,344.6m | | | | |
| Current Op @ | 0600 | Unlatching THRT and | pulling out of I | hole with productio | n riser and control | line umbilical and | d annular access line |
| Planned Op | | Pull out of hole with 5 Xmas tree | 1/2" productio | n riser. Unlatch and | d pull riser and BO | P to surface. Pre | pare to run production |

Summary of Period 0000 to 2400 Hrs

Completed pre-submergence tests on THRT. Ran completion assy and hanger on 5 1/2" production riser. Landed and tested hanger from above to 3000 psi - OK.Rigged up slickline BOP and lubricator. Set HF-1 packer and tested down annulus - OK. Checked CIV opening pressure. Set XSTT plug in X nipple below AHC packer. Attempt to pressure up tubing to set AHC packer

Operations For Period 0000 Hrs to 2400 Hrs on 25 Sep 2005

| Phse | Cls (RC) | Ор | From | То | Hrs | Depth | Activity Description |
|------|-------------|-----|------|------|------|----------|---|
| С | Р | PT | 0000 | 0100 | 1.00 | 3,414.0m | Continue conducting tubing hanger pre-submergence tests as per completion program. |
| С | TP (VE) | PT | 0100 | 0300 | 2.00 | 3,414.0m | Had leak while testing annulus access hose to 5000 psi. Repaired leak on hose connection at annulus access hose reel. Re-tested annulus access line - leak on annulus hose connection above THRT. Repaired same. Brought shuttle table and BJ retractable slips to rig floor and function tested - OK |
| С | Р | PT | 0300 | 0400 | 1.00 | 3,414.0m | Continued with tubing hanger pre-submergence pressure tests as per completion program. |
| С | Ρ | RIC | 0400 | 0500 | 1.00 | 3,414.0m | Removed temporary annulus plugs from hanger. Completed final positioning of shuttle table. Set THRT and completion string in BJ retractable slips. Changed out 5 1/2" tubing side door elevators for 5 1/2" air powered elevators. |
| С | Ρ | RIC | 0500 | 1030 | 5.50 | 3,414.0m | Ran in hole with completion assy, tubing hanger and THRT on 5 1/2" production riser from derrick installing control line umbilical and annulus access hose clamps. Picked up single of 5 1/2" tubing from deck, made up XO to Expro wireline and laid back down on deck. Installed padeye sub to TDS for air powered chain block. Completed running 5 1/2" production tubing from deck. |
| С | Ρ | RIC | 1030 | 1430 | 4.00 | 3,414.0m | Made up air operated chain block to padeye sub on TDS. Connected long bails to TDS. Picked up single of 5 1/2" tubing with XO installedf from deck. Ran in hole and landed out tubing hanger. |
| С | Р | PT | 1430 | 1500 | 0.50 | 3,414.0m | Broke circulation with Dowell down kill line and tested surface lines - OK. Tested top of hanger against closed lower annular to 3000 psi for 10 mins - OK |
| С | Р | RIC | 1500 | 1530 | 0.50 | 3,414.0m | Latched hanger and confirmed with 50K overpull - OK |
| С | Р | SLK | 1530 | 1700 | 1.50 | 3,414.0m | Rigged up slickline BOP's and lubricator on top of production riser |
| С | Ρ | PT | 1700 | 1830 | 1.50 | 3,414.0m | Tested surface lines to 5000 psi - OK Pressured up down tubing against closed lubricator valve to 500 psi to confirm pressure integrity - OK. Increased tubing pressure to 5000 psi in stages to set upper (HF-1) production packer and held for 15 mins - OK |
| С | Ρ | PT | 1830 | 1930 | 1.00 | 3,414.0m | Bled tubing pressure back down to 4500 psi and locked pressure in. Pressured up down annular access line to 4500 psi to confirm HF-1 packer set and pressure test tubing hanger from below. Held pressure down annulus side of packer for 30 mins - good test |
| С | Ρ | PT | 1930 | 2000 | 0.50 | 3,414.0m | Bled down both tubing and annulus pressures. Pressured up on annulus side only to confirm CIV opening pressure. CIV took 650 psi to open. Pumped 1.5 bbls through CIV Bled down all pressure. |
| С | Ρ | SLK | 2000 | 2230 | 2.50 | 3,414.0m | Opened lubricator valve on completion downhole. Ran in hole with slickline to set XSTT plug in 2.75" X - nipple below lower (AHC) packer. |



Anzon Australia

| Phse | Cls (RC) | Ор | From | То | Hrs | Depth | | | Activity I | Description | | | | | |
|---------|-------------|------------------|----------|-------------|-----------|--------------|---|--|----------------------------|--|----------------------|------------|--|--|--|
| | | | | | | | Had to pump Set plug in X | | h Dowell as plu | g would not pas | s HF-1 packe | r or ICV. | | | |
| С | TP (VE) | PT | 2230 | 2400 | 1.50 | 3,414.0m | integrity of tu Tested surface Pressured up | Attempted to pressure up tubing on top of XSTT plug to 500 psi to confirm pressure integrity of tubing string - pressure leaking off. Tested surface lines to 5000 psi - OK Pressured up tubing and down annulus at same time to 500 psi - pressure holding. Suspect slight leak at CIV. | | | | | | | |
| Opera | tions I | For Pe | riod 0 | 000 Hrs | s to 06 | 00 Hrs o | n 26 Sep 20 | 05 | | | | | | | |
| Phse | Cls (RC) | Ор | From | То | Hrs | Depth | | | Activity I | Description | | | | | |
| С | Ρ | PT | 0000 | 0100 | 1.00 | 3,414.0m | CIV. Pressured up holding OK. Continued to | o down tubing t | to 500 psi to cor | annulus access nfirm tubing pre to 5000psi and | ssure integrity | - pressure | | | |
| С | Р | SLK | 0100 | 0200 | 1.00 | 3,414.0m | | hole with slick kline tools in lu | line and XSTT publicator. | blug. | | | | | |
| С | Ρ | PT | 0200 | 0300 | 1.00 | 3,414.0m | | | | | | | | | |
| С | Р | RPP | 0300 | 0400 | 1.00 | 3,414.0m | Ran in hole w | with slickline ar | nd set 4" ARH p | lug and prong ir | n tubing hange | er | | | |
| С | Ρ | PT | 0400 | 0430 | 0.50 | 3,414.0m | to test plug - | OK | · | H plug to 500 / 5 | • | | | | |
| С | Р | SLK | 0430 | 0500 | 0.50 | 3,414.0m | Bled down all pressure from tubing above closed downhole lubricator valve. Rigged down slickline lubricator and BOP from production tubing | | | | | | | | |
| C | Ρ | RR2 | 0500 | 0600 | 1.00 | 3,414.0m | | | | | | | | | |
| Phase | e Data | to 240 | 0hrs, | 25 Sep | 2005 | | | | | | | | | | |
| Phase | | | | | | | Phase Hrs | Start On | Finish On | Cum Hrs | Cum Days | Max Depth | | | |
| | | -UP/PRI | ESPUD(| RM) | | | | 06 Aug 2005 | 12 Aug 2005 | 154.50 | | | | | |
| ANCHO | `` | .) | | | | | | 12 Aug 2005 | 13 Aug 2005 | 186.50 | | | | | |
| PRESP | ` ' | | | | | | | 13 Aug 2005 | 14 Aug 2005 | 195.00 | | | | | |
| | | | . , | | | | | 14 Aug 2005 | 14 Aug 2005 | 204.50 | | | | | |
| | | HOLE(C | H) | | | | | 14 Aug 2005 | 15 Aug 2005 | 223.00 | | | | | |
| SURFA | | E(SH) SING(SC | ` | | | | | 15 Aug 2005 16 Aug 2005 | 16 Aug 2005 17 Aug 2005 | 256.00 280.50 | | , | | | |
| | | P STAC | | | | | | 17 Aug 2005 | 17 Aug 2005 19 Aug 2005 | 315.50 | | | | | |
| | | PHASE (| . , | | | | | 19 Aug 2005 | 03 Sep 2005 | 332.00 | 13.83 | , | | | |
| | | E HOLE | , | | | | | 19 Aug 2005 | 05 Sep 2005 | 736.49 | 30.68 | | | | |
| | | E CASIN | · · | | | | | 05 Sep 2005 | 07 Sep 2005 | 786.99 | 32.79 | | | | |
| | | HOLE(P | | | | | | 07 Sep 2005 | 11 Sep 2005 | 882.99 | 36.79 | | | | |
| EVALU | ATION F | PHASE (| 2)(E2) | | | | | 11 Sep 2005 | 15 Sep 2005 | 978.49 | 40.77 | 0 3,414.0m | | | |
| PRODU | ICTION | CASING | J/LINER | (PC) | | | | 15 Sep 2005 | 18 Sep 2005 | 1,033.99 | 43.08 | 3 3,414.0m | | | |
| COMPL | ETION(| C) | | | | | 185 | 18 Sep 2005 | 25 Sep 2005 | 1,218.99 | 50.79 | 1 3,414.0m | | | |
| WBM | Data | | | | | | Cost Today | y\$0 | | | | | | | |
| Mud Ty | be: | KCI | Brine A | PI FL: | | | CI: | 560600mg/l | Solids(%vol): | | Viscosity | 26sec/qt | | | |
| Sample | -From: | А | ctive F | ilter-Cake: | : | | K+C*1000: | 10% | H2O: | | PV YP | | | | |
| Time: | | 1 | | THP-FL: | | | Hard/Ca: | 200mg/l | Oil(%): | | Gels 10s | | | | |
| Weight: | | | | ITHP-cake | ·. | | MBT: | | Sand: | | Gels 10m | | | | |
| - | | 0.0 | | ound | | | PM: | | | 10.4 | Fann 003 | | | | |
| Temp: | | | | | | | | . . | pH: | 10.4 Or a h | Fann 006 Fann 100 | | | | |
| | | | | | | | PF: | 0.4 | PHPA: | 0ppb | Fann 200 | | | | |
| Comme | nt | | С | umulative | cost \$ 3 | 93,694.61, S | Sulphite Excess | - 500 ppm | Fann 300 Fann 600 | | | | | | |



Anzon Australia

LIMITED

| Bulk Stocks | | | | | | | | | | | | | | | | | |
|---|------------------|----------------|----------|----------|--------------------------------------|------------|-----------------|----------------------------|---------------------|--|---------|-------------------|----------|-------|---------|---------|---------------|
| | | Name | | | | | | Uni | t | I | n | Used | d | Adju | ıst | Bala | ance |
| Barite Bulk | | | | | | N | 1T | | | | | 0 | | 0 | | | 101.6 |
| Bentonite Bulk | | | | | | N | 1T | | | | | 0 | | | 0 | | 59.8 |
| Diesel | | | | | | | า3 | | | | 0 | | 14 | 0 | | | 465.6 |
| Fresh Water | | | | | | | 13 - 2 | | | | 0 | | 11.1 | | 0 | | 259.4 |
| Drill Water Cement G | | | | | | | า3 1T | | | | 26 0 | | 7.9 0 | | 0 0 | | 342.5 76.1 |
| Cement HT (Silica | a) | | | | | | 1T | | | | 0 | | 0 | | Ū | | 54.0 |
| Pumps | , | | | | | 1 | | | | | | | I | | 1 | | |
| Pump Data - Las | t 24 Hrs | | | | | | Slo | w P | ump Data | a | | | | | | | |
| No. Type | Liner | | Eff (%) | SPM | SP | | | pth | SPM1 | SPP1 | Flow1 | SPM2 | | Flow2 | | | |
| 4 01 11 47005 | (in) | (ppg) | | (SPM) | (ps | si) (bpm | n) (n | n) | (SPM) | (psi) | (bpm) | (SPM) | (psi) | (bpm) | (SPM) | (psi) | (bpm |
| 1 Oilwell 1700P | T 6.000 6.000 | | 97 07 | | | | | | | | | | | | | | |
| 2 National 12-P-160 | 6.000 | | 97 | | | | | | | | | | | | | | |
| 3 National 12-P-160 | 6.000 | | 97 | | | | | | | | | | | | | | |
| Casing | | | | | | · | | | | | | | | | | | <u> </u> |
| OD (in) | | Csg Shoe | MD (m) | Cs | sg Sh | ioe TVD (| m) (| Csg | Landing [(m) | Depth M | D Cs | g Landin TVD (| | h | LOT/ | FIT (pp | g) |
| 30 " | | 209.0 | 00 | 2 | 09.00 | | | 174.5 | 0 | | | | | | | | |
| 13 3/8" | 1000. | | | 00.00 | | 173.53 | | | | 173.53 | | | 14.17 | | | | |
| 9 5/8" 7 " | | 2945. 3413. | | | | | 173.8 2853.9 | | 173.82 2847.43 | | | | 13.10 | | | | |
| Personnel Or | Board | 3413. | .00 | | 30 | 343.59 | | | 2003.8 | 14 | | 2047.4 | 43 | | | | |
| | | Compan | v | | | | Pax | (| | | | Com | ment | | | | |
| DOGC | | | | | | | 45 | | All Diamo | nd Pers | onnel | | | | | | |
| UPSTREAM PET | ROLEUM | | | | | | 9 | | Operator | Personr | nel | | | | | | |
| ESS | | | | | | | 8 | 8 Catering Personnel | | | | | | | | | |
| DOWELL SCHLU | MBERGEF | 2 | | | | | 2 | Cementing | | | | | | | | | |
| FUGRO SURVEY | LTD | | | | | | 6 | | ROV personnel | | | | | | | | |
| WEATHERFORD | | | ΓD | | | | 4 | Casing running Personnel | | | | | | | | | |
| CAMERON AUST | | Y LTD | | | | | 3 | Wellhead personnel | | | | | | | | | |
| WELL DYNAMICS | | | | | | | 1 | Smart completion personnel | | | | | | | | | |
| THE EXPRO GRO | JUP | | | | | Tota | 14 I 92 | | Nell test personnel | | | | | | | | |
| HSE Summar | v | | | | | | _ | | | | | | | | | | |
| Events | - | Date of | flast | Days Sir | nce | | Desc | r. | | | | | Rema | arks | | | |
| Abandon Drill | | 24 Sep 2 | 2005 | 1 Day | | Complete | e abano | don | rig drill | Nighttime Abandon rig drill | | | | | | | |
| BOPE Test | | 18 Sep 2 | | | | Complete | | | | | | 0 | | | | | |
| Environental Issue | e | 21 Sep 2 | | 4 Days | | Environm | nental s | spill | drill | | | | | | | | |
| Fire Drill | | 24 Sep 2 | 2005 | 1 Day | | Rig fire d | rill | | | Nighttime fire drill. Scenario was a fire in the well test | | | | | t | | |
| | | | | | Drill=3, Deck=7, Welder=2, Mech=1 | | | packa | je. | | | | | | | | |
| Man Overboard Drill 10 Sep 2005 15 Days | | | | | Man ove | rboard | drill | | | | | | | | | | |
| STOP Card | | 25 Sep 2 | 2005 | 0 Days | | 9 x corre | ctive, 3 | хр | ositive | | | | | | | | |
| Shakers, Volu | imes an | d Losse | es Dat | а | | | | | | | | | | | | | |
| Available | 2,367bbl | Losses | | 0 | bbl | 01. 1 | Equip |). | | | Desc | cr. | | | Mesh \$ | | V cc |
| Active | 250bb | I | | | | Shaker1 | | | | VSM10 | | | | | | | X 230 |
| | | 1 | | | | Shaker2 | | | | VSM10 | JU | | | | | 4 | X 230 |
| Hole | 923bb | I | | | | Shaker3 | | | | VSM10 | 0 | | | | | | X 230 |



Anzon Australia

LIMITED

| Marine | | | | | | | | | | | |
|------------------|-------------------------------------|----------------------------|--------------|----------------------|--------------|-------------|----------------------------|---------------------------------|---------------|----------|--|
| Weather on | 25 Sep 2005 | 5 | | | | | | Rig Support | | | |
| Visibility | /isibility Wind Speed Wind Dir. Pre | | Pressure | Air Temp. | Wave Height | Wave Dir. | Wave Period | Anchors | Tension (klb) | | |
| 9.0nm | 21kn | 45.0deg | 1,015.0mbar | 16C° | 0.5m | 45.0deg | 3s | 1 | 2 | 56.0 | |
| Rig Dir. | Ris. Tension | VDL | Swell Height | Swell Dir. | Swell Period | Weathe | r Comments | 2 | 2 | 62.0 | |
| • | | | | | 1 | liteane | | 3 | | 36.0 | |
| 253.0deg | 480.00klb | 5,321.80klb | 1.0m | 180.0deg | 8s | _ | | 4 | | 67.0 | |
| | | Com | ments | | | | | 5 | | 69.0 | |
| | | | | | | | | 6 | | 69.0 | |
| | | | | | | | | 7 | | 89.0 | |
| | | | | | | | | 8 | 2 | 95.0 | |
| Vessel | Name A | rrived (Date/1 | | eparted ate/Time) | Sta | atus | | Bulks | | | |
| Far Grip | | 11:30hrs 25th | Sept | | Standby at | rig | Item | Unit | Used | Quantity | |
| | | | | | | | Diesel | M3 | | 455 | |
| | | | | | | | Fresh Water Drill Water | M3 M3 | | 405 | |
| | | | | | | | Cement G | MIS | | 75 | |
| | | | | | | | Cement HT (Silica) | MT | | 0 | |
| | | | | | | | Barite Bulk | MT | | 0 | |
| | | | | | | | Bentonite Bulk Brine | MT BBLS | | 65 | |
| | | | | | | | Dille | DDLO | | | |
| Pacific Sentinel | | 11:45hrs 22nd | l Sept | | Standby ve | ssel at rig | Item | Unit | Used | Quantity | |
| | | | | | | | Diesel | M3 | | 149.7 | |
| | | | | | | | Fresh Water Drill Water | M3 M3 | | 239 | |
| | | | | | | | Cement G | M3 | | 0 | |
| | | | | | | | Cement HT (Silica) | | | 0 | |
| | | | | | | | Barite Bulk | MT | | 0 | |
| | | | | | | | Bentonite Bulk | MT | | 0 | |
| | | | | | | | Brine | BBLS | | 0 | |
| Helicopt | er Movem | ent | | | | | | | | | |
| Flight # | | Company | | Arr/Dep. Tin | ne | Pax | In/Out | Comment | | | |
| 1 | | V HELICOPTE LIA PTY LTD | RS | 1045 / 1110 |) | 5 | / 4 | Refuelled with 441 Itres Jet A1 | | | |